

AB1222 Advisory Group Phase 2A Summary


May 21, 2007

Gary Full - ESPH

Testing Overview

- Installation at Fast Track Site: Sunday 6-May and Monday 7-May.
- Train Session 1: May 7-8 CCW operation (BNSF-NS-CSX-UP)
 - Acquired data, failed control computer replaced, (salvaged data later in week).
 - TTCI provided notch, position, and speed data from instrumented BNSF
- Train Session 2: May 8-9 CCW operation (BNSF-NS-CSX-UP)
 - Generator stopped (**no data**), replaced with van generator for next night
 - Instrumented locomotive (BNSF) replaced due to bearing problem.
- Train Session 3: May 9-10 CW operation (UP-CSX-NS-AAR)
 - Obtained data
 - TTCI provided lap and speed data from bearing temperature station
- Train Session 4: May 10-11 CW operation (UP-CSX-NS-AAR)
 - Obtained data
 - TTCI provided lap and speed data from bearing temperature station
- May 11: De-installed and returned Tucson.

Track Route



Camera boom

Sample head


05.07.2007

Pole not required





05.06.2007



GROUND STATION

Support Trailer

RSD Analyzer in protective enclosure


Accumulator Box

Blower


RSD Mirror in protective enclosure

05.07.2007


NO & SF Notch 8, Position 4 (UP) 5/7-5/8




NO and uv-Smoke Notch 7, Position 4



NO and uv-Smoke Notch 6, Position 4



NO and uv-Smoke Notch 5, Position 4




Valid Notch 8 (5/7-5/8)

BNSF

NS

CSX

UP




Valid (all notches) 5/7-5/8

BNSF

NS

CSX

UP




All Valid 5/9-5/10 (mostly notch 8)

UP

CSX

NS

AAR




All Valid 5/10-5/11

UP

CSX

NS

AAR



Technical Issues

- “Hit Rate”/productivity: (primary risk issue for Phase 2)
 - For positions 2,3, and 4 obtained valid readings for only 30-40% of laps.
 - For Position 1, <20%.
 - Partial Explanations:
 - Loss of 1-hour for RSD maintenance at 00:30.
 - ~10% of records invalidated because of apparent “bounce” of optical train sensor.
 - Ground station fencing should have included a wind barrier.
 - Need to consider displacement “wind effects” generated by the train.

Technical Issues cont.

- Speed measurement subsystem (radar) was disabled/not evaluated. Was disabled because of occasional operating system crashes when connected. Failure of operating system after 1st night may imply the issue was not with the radar system. (Low risk issue for Phase 2).
- Gasoline generator reliability is still an issue. (Low risk issue for Phase 2).
- Night time video is still not acceptable/proven. (Medium risk issue for Phase 2).

Recommendations

- Proceed with Phase 2 deployment in Northern California:
 - Include some engineering contingency support to refine camera system and to identify/correct productivity issues in Roseville Yard and Weimar line haul sites.