

Model Year	Engine Family	Displacement, L	Model Year	Engine Family	Displacement, L
Cummins					
1996	TCE359R6DTRA	5.9	2001	1CEXL0239AAA	3.9
	TCE505R6DTRA	8.3		1CEXL0239AAC	3.9
	TCE505R6DTRB	8.3		1CEXL0239ABA	3.9
	TCE505R6DTRC	8.3		1CEXL0239ACA	3.9
	TCE505R6DTRD	8.3		1CEXL0239ADA	3.9
	TCE661RGDTRA	10.8		1CEXL0239AEA	3.9
	TCE855RGDTRA	14		1CEXL0239AFA	3.9
	TCE855RJDTRA	14		1CEXL0359AAA	5.9
	TCE19.RJDTRA	19		1CEXL0359ABA	5.9
	TCE19.RJDTRB	19		1CEXL0359ABB	5.9
1997	VCE359R6DTRB	5.9	1CEXL0359ABC	5.9	
	VCE505R6DTRA	8.3	1CEXL0359ABD	5.9	
	VCE505R6DTRB	8.3	1CEXL0359ACA	5.9	
	VCE505R6DTRC	8.3	1CEXL0359ADA	5.9	
	VCE505R6DTRD	8.3	1CEXL0505AAA	8.3	
	VCE661RGDTRA	10.8	1CEXL0505ABA	8.3	
	VCE855RGDTRA	14	1CEXL0505ABB	8.3	
	VCE19.RJDTRA	19	1CEXL0505ABC	8.3	
	VCE19.RJDTRB	19	1CEXL0505ACB	8.3	
				1CEXL0505ACC	8.3
1998	WCEXL0359AAA	5.9	1CEXL0505ACD	8.3	
	WCEXL0359ABA	5.9	1CEXL0505ACE	8.3	
	WCEXL0359ABB	5.9	1CEXL0661AAA	10.8	
	WCEXL0505AAA	8.3	1CEXL0661AAB	10.8	
	WCEXL0505ABA	8.3	1CEXL0661AAC	10.8	
	WCEXL0505ABB	8.3	1CEXL0661AAD	10.8	
	WCEXL0505ABC	8.3	1CEXL015.AAA	15	
	WCEXL0505ACA	8.3	1CEXL015.ABA	15	
	WCEXL0661AAA	10.8	1CEXL019.AAB	19	
	WCEXL0855AAA	14	1CEXL019.AAC	19	
	WCEXL0855AAB	14			
	WCEXL019.AAA	19			
	WCEXL019.AAB	19			
			2002	2CEXL0239AAA	3.9
1999	XCEXL0359ABA	5.9	2CEXL0239AAC	3.9	
	XCEXL0359ABB	5.9	2CEXL0239AAE	3.9	
	XCEXL0505AAA	8.3	2CEXL0239ABA	3.9	
	XCEXL0505ABA	8.3	2CEXL0239ACA	3.9	
	XCEXL0505ABB	8.3	2CEXL0239ADA	3.9	
	XCEXL0505ABC	8.3	2CEXL0239AEA	3.9	
	XCEXL0505ACA	8.3	2CEXL0239AFA	3.9	
	XCEXL0661AAA	10.8	2CEXL0359AAA	5.9	
	XCEXL0661AAB	10.8	2CEXL0359ABA	5.9	
	XCEXL0855AAA	14	2CEXL0359ABB	5.9	
	XCEXL0855AAB	14	2CEXL0359ABC	5.9	
	XCEXL019.AAA	19	2CEXL0359ABD	5.9	
	XCEXL019.AAB	19	2CEXL0359ABE	5.9	
				2CEXL0359ACA	5.9
2000	YCEXL0359ABA	5.9	2CEXL0359ADA	5.9	
	YCEXL0359ABB	5.9	2CEXL0505AAA	8.3	
	YCEXL0505AAA	8.3	2CEXL0505ABA	8.3	
	YCEXL0505ABA	8.3	2CEXL0505ABB	8.3	
	YCEXL0505ABB	8.3			

	YCEXL0505ABC	8.3		2CEXL0505ABC	8.3
	YCEXL0505ACA	8.3		2CEXL0505ABD	8.3
	YCEXL0661AAA	10.8		2CEXL0505ACA	8.3
	YCEXL0661AAB	10.8		2CEXL0505ACB	8.3
	YCEXL0855AAA	14		2CEXL0505ACC	8.3
	YCEXL0855AAB	14		2CEXL0505ACD	8.3
	YCEXL015.ABA	15		2CEXL0505ACE	8.3
	YCEXL019.AAA	19		2CEXL0661AAA	10.8
	YCEXL019.AAB	19		2CEXL0661AAB	10.8
				2CEXL0661AAC	10.8
				2CEXL0661AAD	10.8
				2CEXL015.AAA	15
				2CEXL015.AAB	15
				2CEXL015.ABA	15
				2CEXL019.AAB	19
				2CEXL019.AAC	19
Case					
1996	TX9505R6DTRA	8.3	2001	1X9XL0239AAA	3.9
	TX9505R6DTRB	8.3		1X9XL0239AAB	3.9
	TX9505R6DTRC	8.3		1X9XL0239AAC	3.9
1997	VX9505R6DTRA	8.3		1X9XL0239ABA	3.9
	VX9505R6DTRB	8.3		1X9XL0239ACA	3.9
	VX9505R6DTRC	8.3		1X9XL0239ADA	3.9
1998	WX9XL0239ABA	3.9		1X9XL0359AAA	5.9
	WX9XL0239ACA	3.9		1X9XL0359ABA	5.9
	WX9XL0359AAA	5.9		1X9XL0505AAA	8.3
	WX9XL0359ABA	5.9		1X9XL0505ABA	8.3
	WX9XL0505AAA	8.3		1X9XL0505ABB	8.3
	WX9XL0505ABA	8.3		1X9XL0505ABC	8.3
	WX9XL0505ABB	8.3		1X9XL0505ACA	8.3
	WX9XL0505ABC	8.3		1X9XL0505ACC	8.3
	WX9XL0505ACA	8.3	2002	2X9XL0239AAA	3.9
1999	XX9XL0359ABA	5.9		2X9XL0239AAB	3.9
	XX9XL0505AAA	8.3		2X9XL0239AAC	3.9
	XX9XL0505ABA	8.3		2X9XL0239ABA	3.9
	XX9XL0505ABB	8.3		2X9XL0239ACA	3.9
	XX9XL0505ABC	8.3		2X9XL0239ADA	3.9
	XX9XL0505ACA	8.3		2X9XL0359AAA	5.9
2000	YX9XL0359ABA	5.9		2X9XL0359ABA	5.9
	YX9XL0505AAA	8.3		2X9XL0359ABB	5.9
	YX9XL0505ABA	8.3		2X9XL0359ABE	5.9
	YX9XL0505ABB	8.3		2X9XL0505AAA	8.3
	YX9XL0505ABC	8.3		2X9XL0505ABA	8.3
	YX9XL0505ACA	8.3		2X9XL0505ABB	8.3
				2X9XL0505ABC	8.3
				2X9XL0505ABD	8.3
				2X9XL0505ACA	8.3
				2X9XL0505ACC	8.3
Komatsu					
1996	TKD505R6DTRA	8.3	2001	1KLXL0239AAA	3.9
	TKD505R6DTRC	8.3		1KLXL0239ABA	3.9
	TKL11.RZDARA	11		1KLXL0239ACA	3.9

	TKL11.RZDARB	11		1KLXL0359AAA	5.9
	TKL11.RZDARC	11		1KLXL0359ABA	5.9
1997	VKD505R6DTRA	8.3		1KLXL0359ABC	5.9
	VKD505R6DTRC	8.3		1KLXL0359ACA	5.9
1998	WKDXL0239AAA	3.9		1KLXL0505AAA	8.3
	WKDXL0239ABA	3.9		1KLXL0505ABB	8.3
	WKDXL0239ACA	3.9		1KLXL0505ACA	8.3
	WKDXL0359AAA	5.9		1KLXL11.0DA1	11
	WKDXL0359ABA	5.9		1KLXL11.0DB1	11
	WKDXL0505AAA	8.3		1KLXL11.0DC1	11
	WKDXL0505ABB	8.3		1KLXL11.0DD3	11
	WKLXL11.0DA1	11		1KLXL11.0DD4	11
	WKLXL11.0DB1	11	2002	2KLXL0239AAA	3.9
	WKLXL11.0DC1	11		2KLXL0239ABA	3.9
1999	XKDXL0359ABA	5.9		2KLXL0239ACA	3.9
	XKDXL0505AAA	8.3		2KLXL0239ADA	3.9
	XKDXL0505ABB	8.3		2KLXL0359AAA	5.9
	XKDXL0505ACA	8.3		2KLXL0359ABA	5.9
	XKLXL11.0DA1	11		2KLXL0359ABC	5.9
	XKLXL11.0DB1	11		2KLXL0359ACA	5.9
	XKLXL11.0DC1	11		2KLXL0505AAA	8.3
2000	YKLXL0359ABA	5.9		2KLXL0505ABB	8.3
	YKLXL0505AAA	8.3		2KLXL0505ABD	8.3
	YKLXL0505ABB	8.3		2KLXL0505ACA	8.3
	YKLXL0505ACA	8.3		2KLXL11.0DA1	11
	YKLXL11.0DA1	11		2KLXL11.0DB1	11
	YKLXL11.0DB1	11		2KLXL11.0DC1	11
	YKLXL11.0DC1	11		2KLXL11.0DC3	11
				2KLXL11.0DD3	11
				2KLXL11.0DD4	11
				2KLXL11.0DD5	11
				2KLXL11.0DD6	11
Navistar (International)					
1996	TNV466R6DARA	7.6	1999	XNVXL0466ANA	7.6
	TNV466R6DARB	7.6		XNVXL0466BNA	7.6
	TNV466R6DASC	7.6		XNVXL0530ANA	8.7
	TNV466R6DASD	7.6		XNVXL0530ANB	8.7
	TNV530R6DARA	8.7		XNVXL0530ANC	8.7
	TNV530R6DARB	8.7		XNVXL0530AND	8.7
	TNV530R6DASD	8.7		XNVXL0530BNA	8.7
	TNV530R8DASC	8.7		XNVXL0530BNB	8.7
	TNV530R8DASE	8.7		XNVXL0530BNC	8.7
				XNVXL0530BND	8.7
1997	VNV466R6DASC	7.6	2000	YNVXL0466ANA	7.6
	VNV466R6DASD	7.6		YNVXL0530ANA	8.7
	VNV530R6DARA	8.7		YNVXL0530ANB	8.7
	VNV530R6DARB	8.7		YNVXL0530ANC	8.7
	VNV530R6DASC	8.7		YNVXL0530AND	8.7
	VNV530R6DASD	8.7			
	VNV530R8DARA	8.7	2001	1NVXL0466ANA	7.6
	VNV530R8DASC	8.7		1NVXL0530ANA	8.7
	VNV530R8DASE	8.7		1NVXL0530ANB	8.7
1998	WNVXL0466BNA	7.6		1NVXL0530ANC	8.7

WNVXL0530ANA	8.7	1NVXL0530AND	8.7
WNVXL0530ANB	8.7	1NVXL0530ANE	8.7
WNVXL0530BNA	8.7	1NVXL0530ANF	8.7
WNVXL0530BNB	8.7	2002 2NVXL0466ANA	7.6
WNVXL0530BNC	8.7	2NVXL0530ANA	8.7
WNVXL0530BND	8.7	2NVXL0530ANB	8.7
		2NVXL0530ANC	8.7
		2NVXL0530AND	8.7
		2NVXL0530ANE	8.7
		2NVXL0530ANF	8.7