

Board Administration and Regulatory Coordination Unit

Division 3. Air Resources Board

Chapter 1. Air Resources Board

Subchapter 8. Compliance with Nonvehicular Emission Standards

**Article 2. Test Methods for Determining Compliance
with District Nonvehicular Emission Standards**

§ 94119. Method 5E--Particulate Matter Emissions (Wool Fiberglass).

The test method for determining wool fiberglass particulate emissions is set forth in the Air Resources Board's Method 5E, Determination of Particulate Emissions from the Wool Fiberglass Insulation Manufacturing Industry, adopted March 28, 1986, as last amended July 1, 1999, which is incorporated herein by reference.

NOTE: Authority cited: Sections 39600, 39601 and 39607, Health and Safety Code. Reference: Sections 39515, 39516, 39605, 39607 and 40001, Health and Safety Code.

REFERENCE