

Board Administration and Regulatory Coordination Unit

Division 3. Air Resources Board

Chapter 1. Air Resources Board

Subchapter 8. Compliance with Nonvehicular Emission Standards

**Article 2. Test Methods for Determining Compliance
with District Nonvehicular Emission Standards**

§ 94128. Method 401--Determination of the Weight Percent of Volatile Organic Compounds in Waste Products (Gravimetric Purge and Trap).

The test method for determining the weight percent of volatile organic compounds in waste is set forth in the Air Resources Board's Method 401, Determination of the Weight Percent of Volatile Organic Compounds in Waste Products, adopted March 28, 1986.

NOTE: Authority cited: Sections 39600, 39601 and 39607, Health and Safety Code. Reference: Sections 39515, 39516, 39605, 39607 and 40001, Health and Safety Code.

REFERENCE