

Board Administration and Regulatory Coordination Unit

Division 3. Air Resources Board

Chapter 1. Air Resources Board

Subchapter 8. Compliance with Nonvehicular Emission Standards

**Article 2. Test Methods for Determining Compliance
with District Nonvehicular Emission Standards**

§ 94134. Method 424-Inorganic Particulate and Gaseous Cadmium Emissions.

The test method for determining inorganic particulate and gaseous cadmium emissions is set forth in the Air Resources Board's Method 424, Determination of Inorganic Particulate and Gaseous Cadmium Emissions from Stationary Sources, adopted January 22, 1987, which is incorporated herein by reference.

NOTE: Authority cited: Sections 39600, 39601 and 39607, Health and Safety Code. Reference: Sections 39515, 39516, 39605, 39607, 39666 and 40001, Health and Safety Code.

REFERENCE