

Board Administration and Regulatory Coordination Unit

Division 3. Air Resources Board

Chapter 1. Air Resources Board

Subchapter 8. Compliance with Nonvehicular Emission Standards

**Article 2. Test Methods for Determining Compliance
with District Nonvehicular Emission Standards**

§ 94140. Method 501--Determination of Size Distribution of Particulate Matter from Stationary Sources.

The test method for determining size distribution of particulate matter emissions is set forth in the Air Resources board's Method 501, Determination of Size Distribution of Particulate Matter Emissions from Stationary Sources, adopted March 23, 1988, as last amended September 12, 1990, which is incorporated herein by reference.

NOTE: Authority cited: Sections 39600, 39601 and 39607, Health and Safety Code. Reference: Sections 39515, 39516, 39605, 39607 and 40001, Health and Safety Code.

REFERENCE